


WALLS AND CONDUIT—SUGAR CONE FACILITY ULTRAVAPOR DEMONSTRATION RESULTS

October 2007

Equipment demonstrated: Special II 18 KW UltraVapor unit, vacuum, long lance, brush tool, 25 cm suction tool, 35 cm floor suction tool and 35 cm squeegee



Top photo shows cinder block wall with several years of oil, grease and dirt build up. At upper right UltraVapor with suction easily removes the build up revealing the white paint beneath. At right UltraVapor with a squeegee tool makes even faster work of the cleaning. The small amount of water and oil squeegeed to the floor was recovered with a floor suction tool leaving the floor clean and dry.



Photos below show the build up of oil and dirt on the conduit coming from this 600 volt electrical panel. UltraVapor easily and safely cleans the conduit without having to shut off facility power.

